


## Product Change Notification (PCN)

PCN NUMBER PCN24006	DATE 10/07/2024
CUSTOMER(S) All	
PROJECT(S) AFFECTED 32128A FC BW-3, 32128A FC BW-RGB	
EFFECTIVE DATE / OTHER REFERENCE 11/01/2024	

DESCRIPTION OF CHANGE(S)	
REASON FOR CHANGE(S) Driver IC ST7565V is EOL and production location moved.	
BEFORE CHANGE(S) Driver IC ST7565V.	AFTER CHANGE(S) Driver IC ST7565R-G. Capacitors at DC/DC converter pins should not be polarized. Minor cosmetic differences might be noticeable.

Thank you for your continued interest in SEACOMP products and services. For additional assistance or questions, please contact your Account Manager or SEACOMP Customer Service at sales@seacomp.com.

Sincerely,  
 For and on behalf of SEACOMP



Bjorn Hilliges, Technical Director - Europe